



Landslide Repair in the Southwestern United States

Derrick Hayes, PE, GE, Regional Engineer

Justin Petersen, PE, Regional Engineer

Landslide Repair in the Southwestern United States

- NMDOT Hwy 76 RSS Wall Distress
- 38 Road Improvements
- Alpine State Hwy (CA-4) Slide Repair
- Bartlett Springs Rd Shoulder Repair
- Mt. Hamilton (CA-130) Road Stabilization


Landslide Repair in the Southwestern United States



“Gentlemen,
We Are Out Of Money;
Now We Must Think.”

-Winston Churchill

NMDOT Hwy 76 RSS Wall Distress




NMDOT Hwy 76 RSS Wall Distress



NMDOT Hwy 76 RSS Wall Distress




NMDOT Hwy 76 RSS Wall Distress



Legend:	
20-ft Self-Drilling SuperNail®	○
30-ft Self-Drilling SuperNail®	□

NMDOT Hwy 76 RSS Wall Distress



NMDOT Hwy 76 RSS Wall Distress



NMDOT Hwy 76 RSS Wall Distress




NMDOT Hwy 76 RSS Wall Distress



NMDOT Hwy 76 RSS Wall Distress



38 Road Improvements MSE Wall Repair




38 Road Improvements MSE Wall Repair



38 Road Improvements MSE Wall Repair



38 Road Improvements MSE Wall Repair



38 Road Improvements MSE Wall Repair




38 Road Improvements MSE Wall Repair



38 Road Improvements MSE Wall Repair




Alpine State Hwy (CA-4) Slide Repair



Alpine State Hwy (CA-4) Slide Repair



Alpine State Hwy (CA-4) Slide Repair




Alpine State Hwy (CA-4) Slide Repair



Alpine State Hwy (CA-4) Slide Repair




Bartlett Springs Rd. Shoulder Repair




Bartlett Springs Rd. Shoulder Repair



Bartlett Springs Rd. Shoulder Repair



Bartlett Springs Rd. Shoulder Repair



This drawing is furnished solely for the use of or in connection with this project and the proprietary information shown herein is not to be transmitted to any other organization without specific authorization by GeoStabilization International (GSI). The design is only valid if constructed and supervised by GSI or its authorized subcontractor.

Sheet Revision		
Date:	By:	
2-11-15	As Constructed	DRH

Typical Cross-Section & Elevation Detail	
Project:	Bartlett Springs Road
Drawn By:	DRH
Date:	January 30, 2015
Checked By:	CL

Project No./Code:	140271CA01
Sheet No.:	3




GeoStabilization International
1809 S Street Ste. 101-203
Sacramento, CA 95811
P: (916) 913-0748
F: (970) 245.7737
www.geostabilization.com

Bartlett Springs Rd. Shoulder Repair



Mt. Hamilton (CA-130) Road Stabilization



Mt. Hamilton (CA-130) Road Stabilization




Mt. Hamilton (CA-130) Road Stabilization




Mt. Hamilton (CA-130) Road Stabilization



Mt. Hamilton (CA-130) Road Stabilization



Mt. Hamilton (CA-130) Road Stabilization



Mt. Hamilton (CA-130) Road Stabilization



Landslide Repair in the Southwestern United States



“Innovation
Distinguishes Between A
Leader And A Follower.”

- *Steve Jobs*